

IPX Series

Firmware Release Notes

Released 04.02.2021

Release version 1.6.0 contains the following updates:

Features

- Default password updated to last 6 digits of Mac address to comply with State of California SB-327
- Improvements to WebUI
- EQ curves based on model type
- When SIP is enabled in InformaCast, the IPX speaker, microphone, and pre-recorded volumes will be set to the InformaCast settings
- Addition of model: IP-DMF

Bugs

- Fixed SIP beep while registered to InformaCast
- Fixed volume of intercom chime when using InformaCast full duplex
- Fixed level adjustment for GCK intercom calls
- Fixed strobe issues when GCK pre-recorded or live announcement plays
- Fixed bug with GPI trigger type when calling an extension to dial
- Increased resistance to static discharge
- Fixed strobe issues with IP-DD
- Other bug fixes and performance improvements

List of Known Issues

- Auto-provisioning is not currently activated

Firmware Update Instructions

Note: IPX endpoints on any firmware version prior to 1.0.9 will need to update to version 1.0.9 before updating to version 1.3.1.

IPX endpoints on any firmware version between 1.0.9 and 1.3.0 will need to be updated to version 1.3.1 prior to updating to version 1.6.0.

IPX endpoints on firmware version 1.3.1 or higher can be updated directly to firmware version 1.6.0.

Note: When updating IPX endpoints, AtlasIED recommends using the AtlasIED Discover Application.

Firmware version 1.0.9 (Build# 530) is the minimum required version for update with AtlasIED Discover Application.

Firmware version 1.2.0 is the minimum required version for updating from the WebUI.

IMPORTANT: Do NOT reboot the device during this process until it is fully updated. Multiple reboots may occur automatically as the endpoint installs firmware.

Updating Firmware with the AtlasIED Discover Application

1. Download the AtlasIED Discover Quick Start Guide
 - i. The AtlasIED Discover Quick Start Guide can be accessed through the following link
<http://mitk.co/NLD>
2. Download the AtlasIED Discover App IPX Firmware 1.6.0 File
 - i. The AtlasIED Discover App IPX Firmware 1.6.0 can be accessed through the following link
<http://mitk.co/NLE>
3. Follow the instructions found in the AtlasIED Discover Quick Start Guide.

For additional support AtlasIED Tech Support can be reached at 1-800-876-3333 or www.atlasied.com/support